


REPLACEMENT PART OF GOUGING TORCH

TMA^{Ti}C[®]

K 4000



- 1. INSULATOR ASSY P/NO. AW-K 40401
- 2. SCREW P/NO. AW-K 40302
- 3. UPPER ARM P/NO. AW-K 40306
- 4. SCREW P/NO. AW-K40311
- 5. SPRING P/NO. AW-K 40307
- 6. LEVER ASSY P/NO. AW-K 40406
- 7. BODY P/NO. AW-K 40407
- 8. HEAD ASSY P/NO. AW-K 40304
- 9. SCREW P/NO. AW-K 40305
- 10. DOWEL PIN P/NO. AW-K 40312
- 11. SPOOL ASSY P/NO. AW-K 40313
- 12. BONNET P/NO. AW-K 40314
- 13. GOUGING HOSE ONLY P/NO. AW-K 40326-100 (1.00M)
- 14. HANDLE P/NO. AW-K 40414
- 15. SWIVEL CABLE ASSY P/NO. AW-K 40415
- 16. TORCH END CONNECTOR ASSY P/NO. AW-K 40416
- 17. FEMALE CONNECTOR ASSY P/NO. AW-K 40417
- 18. CONDUCTOR ASSY P/NO. AW-K 40418
- 19. SCREW P/NO. AW-K 40302
- 20. CLAMP P/NO. AW-K 40328
- 21. CLAMP P/NO. AW-K 40328
- 22. INSULATION BOOT P/NO. AW-K 40329
- 23. COPPER SLEEVE P/NO. AW-K 40323
- 31. GOUGING HOSE CRIMPING TOOL P/NO. TM-K3-001



ABRAWELD (S) PTE LTD

No. 1 Upper Aljunied Link, Blk A, #08-06 Joo Seng Warehouse, Singapore 367901
 Tel : +65 68586841 Fax : +65 68586842 email : enquiry@abraweld.com.sg